State of the state

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0931

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Contact: Murley, Rickey

Address:

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone:

Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-424-7242

Client Name: Client ID:

Alt. Client ID: 16016SW-0931

Work Order (Bid Form)

Work Order Name

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0 Page 1 of 6

Measures

	Measure 1 Infilt	tration Redctn		**************************************	Componen	ıts		1	nspected
C	Comment								
					Estimated	I		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal crown molding in kitchen, Seal back wall and pipe under sink, Seal wall paneling around door. Seal pipes and wall behind cook stove	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal pipes and wall under vanity. Add strip and seal over tub at seam	Each	1	Transport			The state of the s	
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal ceiling in in back bedroom, Seal crown molding in living room, Seal breaker box	Each	1	TETATATA AND AND AND AND AND AND AND AND AND AN				
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Caulk all windows and glaze as needed (loose or missing glazing)	Each	1					
8	Labor	Labor	Hour					ALTER AND THE STATE OF THE STAT	778 -77 NALALAMAN NASSAMAN AND SANSAMAN AND
C	ther Detail		·	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
								TO STATE OF THE ST	
L						A sea and the			
				Measure	Sub Total:		S	ub Total:	
	Field Notes:								

Alt. Client ID: 16016SW-0931

Report Run On: 5/25/2010

Page 2 of 6

		H Pipe Insulation			Componen	ts			Inspected
C	Comment				Estimateo	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	Labor	Each	1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:				, , ,				
			Services and when the man and the forms of manufactures are and \$4.50 for \$5.						
		Ins. R-30			Componen	ts A1			Inspected
C	omment				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Insulation	Attic Insulation - Blown	SqFt	696					, 013,
		Cellulose - Add 10 inches	·						
2	Labor	Labor	Hour						
3	Construction	Install attic access	Each	1					Avenue
	Materials/Hardwar e	cover, repair ceiling in kitchen approx 1x3 area, Hall approx 4x6 area and front bedroom approx 4x8 area before insulating						Innumeration -	
4	Labor	Labor	Hour						
O	Other Detail					<u> </u>			

			I	Measure	Sub Total:		S	Sub Total:	
Γ	Field Notes:	AND			- Luc	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		1.	1

Client Name:

Client ID:

Alt. Client ID: 16016SW-0931

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 6

Measure 4 CO N	Monitor is Needed			Componen	ts		I.	nspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1			1		
2 Labor	Labor	Hour	1					
Other Detail						7 /		
Addition to the state of the st				TO A POLICE AND A STATE AND A	M. MARANA III PARTITION III			
			Measur	e Sub Total:			Sub Total:	
Measure 5 Fix A	Any Other Heating Syste	em Proble	em	Componen	ts			nspected
	Any Other Heating Systonic old heater and place heater			Component	fs	Andrew (I	l Actual	nspected
Comment Remove				t	ts Total	Qty		nspected
Comment Remove # Material / Labor	old heater and place he	ater in sar	ne spo	t Estimated		Qty	Actual	
Comment Remove # Material / Labor 1 Health and Safety Items	old heater and place heater Description / Comment Counter Flow Direct Vent Natural Gas Heater	ater in sar <i>Unit</i> s	ne spo Qty	t Estimated		Qty	Actual	
Comment Remove # Material / Labor 1 Health and Safety Items	old heater and place heater Description / Comment Counter Flow Direct Vent Natural Gas Heater 40-45 KBTU	ater in sar <i>Units</i> Each	Qty	t Estimated		Qty	Actual	
Comment Remove # Material / Labor 1 Health and Safety Items 2 Labor	old heater and place heater Description / Comment Counter Flow Direct Vent Natural Gas Heater 40-45 KBTU	ater in sar <i>Units</i> Each	Qty	t Estimated		Qty	Actual	
Comment Remove # Material / Labor 1 Health and Safety Items 2 Labor	old heater and place heater Description / Comment Counter Flow Direct Vent Natural Gas Heater 40-45 KBTU	ater in sar <i>Units</i> Each	Qty	t Estimated		Qty	Actual	
Comment Remove # Material / Labor 1 Health and Safety Items 2 Labor	old heater and place heater Description / Comment Counter Flow Direct Vent Natural Gas Heater 40-45 KBTU	Units Each Hour	Qty 1	t Estimated			Actual	

Report Run On: 5/25/2010

	Measure 6 Insta	all Bathroom Exhaust F	an		Componen	ts		i	Inspected
_					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	1					
2	Labor	Labor	Hour	1	######################################				
	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 7 Insta	all Kitchen Exhaust Far	1		Componen		- A.P. A.		Inspected
					Estimated			Actual	
	Material / Labor Health and Safety Items	Description / Comment Kitchen exhaust fan	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
2	Labor	Labor	Hour	1			A Laboratory and the state of t		
(Other Detail						11 Y 12 Y		
	Field Notes:			Measur	e Sub Total:			Sub Total:	

	Measure 8 Pres	sureRelief Piping Nee	ded		Componen	ts		li	nspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1	de la constantina del constantina de la constantina de la constantina del constantina de la constantin				
2	Labor	Labor	Hour	1					
(Other Detail					ANT-2007.	-,		
			Measur	e Sub Total:			Sub Total:		
	Field Notes:								
Į									
			Work O	rder Gra	nd Total:		Gran	d Total:	